



tap can cause problems with the thread cutting oversize, so it is important to perform an inspection with a GO thread plug gauge after tapping.