


• The dimensions of machined threads are guaranteed at the time of shipment from the manufacturer, so even non-skilled workers can perform accurate machining.

• Solid die: D is not split and does not spread, so the dimensions of the machined thread are very stable.

• There is no thread distortion, so there is less deviation of the outer diameter and less surface distortion. There is no run-out, so an accuratelly machined thread with a better surface finish can be obtained.

• Since the die material is HSS (High Speed Tool Steel), longer tool life can be obtained.



You will need to fine-tune the adjustment screws yourself to get the optimum external thread dimensions.